



OULGARET MUNICIPALITY PUDUCHERRY – 5



JAL SHAKTI ABHIYAN

SOP FOR INTERVENTION – 2

Renovation of traditional and other water bodies / tanks



INDEX

Sl.No.	Description	Page No.
1	Introduction	3
2	1. Tamaraikulam, Sanjeevi Nagar	5
3	2. Thanthiriyarkulam, Western side of Irumbai - Nesal road, Alankuppam.	8
4	3. Pillaiyarkulam, Alankuppam	11
5	4. Vannarakuttai, Eastern side of Irumbai - Nesal road, Alankuppam.	14
6	5. Velankannikulam, Opp. to Angalammarkoil, Irumbai road, Alankuppam	17
7	6. Kainthakuttai, Opp. to Law College, Peria Kalapet.	20
8	7. Kulam, Opp. to Law College, Peria Kalapet.	23
9	8. Gangaianman Kulam, Eastern side of ECR, Ganapathichettykulam, Near Gangaianman temple.	26
10	9. Kalapet Nedugkulam, Eastern side of ECR, Opp. to Selliammarkoil, Peria Kalapet.	29
11	10. Poiyakulam, Pakkamudayanpet	32
12	11. Vannankulam, Southern side of Vazhudavur road and Angalammarkoil	35
13	12. Thakanamkulam, Southern side of Vazhudavur road, Backside of Sri Ram Thirumana Nilayam	38
14	13. Kulam, Muthupillaipalayam	41
15	14. Tamaraikulam, Muthupillaipalayam	44
16	15. Kulam, Southern side of Christ College	47
17	16. Kannikuttai, Backside of Vasantharaja Theatre, Moolakulam	50
18	17. Moolakulam, Moolakulam	53
19	18. Alli Kuttai, Adikesavan Nagar, Moolakulam	56
20	19. Thagana Kuttai, Thakkakuttai, Arumbarthapuram	59
21	20. AyeeKulam, Muthiraiyarpalayam	62

22	21. Vannankulam, Govindanpet	65
23	22. Peria Kulam, Kavundanpalayam	68
24	23. Vannankulam, Kamban Nagar, Reddiarpalayam	71
25	24. Periyavana Madu, Behind the Parvathi Thirumana Nilayam	74
26	25. Krishnan Kuttai, Pakkamudayanpet	77
27	26. Poonkulam, Opp. to Hotel Annamalai, Adj. to Subramania swamy Koil, Saram	80
28	27. Kuttai, Adj. to ECR Opp. to Sree Raja Rajeswari Thirumana Nilayam	83
29	28. Paracheri Maduvu, Opp. to Latha Steel House, ECR	86
30	29. Kuttai, Opp. to Latha Steel House, ECR	89
31	30. Vengataraiya Pillai Maduvu, Dobighana	92
32	31. Vengadasalam Pillai Madu, Maduvupet, Adjacent to ECR	95
33	32. Vannan Kulam, Maduvupet	98
34	33. Oural Kuttai, Opp. to Orange Restaurant at ECR	101
35	34. Chetty Kulam, Backside of Old Ambiga Theatre	104
36	35. Pillaiyarkoil kulam, Opp. to Lawspet Police Station	107
37	36. Villi Madu, Adj. to Jayaram Garden, Behind MVR Hospital, ECR	110
38	37. Vannan Madu, Adj. to Vivekanada HSS, Northern side of ECR	113
39	Conclusion	116
40	Annexure – A (Abstract of Proposed Estimates)	117
41	Annexure – B (Abstract of Non - Proposed Ponds)	118

INTRODUCTION

SOP FOR INTERVENTION – 2

Renovation of traditional and other water bodies / Tanks

Oulgaret Municipality is the largest Urban Local body in Puducherry State having an area extent of 36.7 Sq. Km and a population of 3,00,150 as per 2011 Census. Traditionally the surface water bodies, primarily 37 ponds were the main source of drinking water. During the French regime the area's prime occupation was agriculture. Oulgaret was exemplary in its water management practices which preserved the water bodies for rural prosperity through reliable irrigation, ground water recharge maintaining bio diversity and flood protection. All the water bodies were affluent with surplus water always leaking over the bunds, hence the name Ozhukarai (meaning leaking bund in Tamil).

It is lamentable that many of these water bodies have gone into disuse because of the over dependence on ground water for irrigation and drinking water.

The survival instinct of the over growing population, owing to its inability to feel the preciousness of water bodies has resulted in the present sad state of ponds. Inadequate maintenance, encroachments, diversion of irrigation of lands for construction purpose are the prime causes for neglect of water bodies.

The Jal Shakti Abhiyan launched in 1st July 2019 emphasises the significance of surface water bodies and warrants the immediate intervention of Local bodies by undertaking focused efforts to inventorize, restore and rejuvenate traditional as well as other water bodies and tanks with people's participation.

In accordance with the guidelines issued in the booklet of Department of Drinking Water and Sanitation, Ministry of Jal Shakti the following steps are to be taken to rejuvenate the ponds in the purview of this Municipality.

1. Identify the number of water bodies owned by different agencies irrigation/Panchayat raj etc)
2. Identify traditional tanks with district Support
3. Inventorize such traditional water bodies and other water bodies capturing their geo-coordinates, sizes, water spread area, inlet channel details etc.

4. Select water bodies in such a way that watershed activities are taken up/likely to be taken up in their catchment area.
5. Removal of encroachment and marking of land boundaries.
6. Repair of conveyance systems and feeder channels and Strengthening of bund(s)
7. Repair of weirs and sluices (if applicable)
8. De-silting to increase tank storage capacity and use the silt in farms. Farmers can be encouraged to volunteer for this activity using their tractors/carts etc.
9. Improvement of catchment areas of tank by undertaking watershed works(planting trees to arrest the soil erosion leading to silting of water bodies,
10. Promotion of conjunctive use of surface and groundwater (if groundwater is available)
11. Community participation through Water User Associations for post rejuvenation sustainable management.
12. Awareness generation and Capacity Building of communities, in better water management and development of tourism, cultural activities, etc.
13. Regulations by local bodies to avoid encroachments and its strict implementation

The details of all the 37 ponds viz., its present condition, survey particulars, Google locations are also furnished.

1. Thamaraikulam, Sanjeevi Nagar

Thamaraikulam is located at Sanjeevi Nagar in Kalapet Assembly Constituency.


As per the Revenue Records, this pond is situated at R.S. No. 18/14 of Alankuppam Revenue Village to an extent of 01-63-50 HAC.

This is a rain water catchment pond. At present this pond is dry. The boundaries of the pond have to be demarcated to ascertain the encroachments. If desilting work is done in this pond before the forthcoming monsoon period, this will increase the storage capacity of the pond and the ground water table will be increased which in turn increase the yield of the borewells which are adjacent to this pond which are used for drinking water supply and agriculture.


Proposal

1. Desilting of pond	– Rs. 6,00,000
2. Strengthening of bund	– Rs. 2,00,000
3. Cleaning the inlet channel	<u>– Rs. 2,00,000</u>
Total	<u>– Rs.10,00,000</u>

FMB Sketch:



Existing condition of Thamaraikulam and its Google Location:



2. Thanthiriyar Kulam, Western side of Irumbai - Nesal road, Alankuppam.

Thanthiriyar kulam is located at Alankuppam on the Western side of the Irumbai-Nesal road in Kalapet Assembly Constituency.


As per the Revenue Records, this pond is situated at R.S. No. 35/2 of Alankuppam Revenue Village to an extent of 01-36-00 HAC.

This is a rain water catchment pond. At present this pond is dry and there are some encroachments on the eastern side of the pond. If desilting work is done in this pond before the forthcoming monsoon period, this will increase the storage capacity of the pond and the ground water table will be increased which inturn increase the yield of the borewells which are adjacent to this pond which are used for drinking water supply and agriculture. Further, this pond is also used for fish culture.


Proposal

1. Desilting of pond	– Rs. 5,50,000
2. Strengthening of bund	– Rs. 2,00,000
3. Cleaning the inlet channel	<u>– Rs. 25,000</u>
Total	<u>– Rs. 7,75,000</u>

FMB Sketch:



Existing condition of Thanthiriyarkulam and its Google Location:



3. Pillaiyarkulam, Alankuppam

Pillaiyarkulam is located at Alankuppam on the Eastern side of Pudu nagar along the Southern side of Alankuppam - Sanjeevi Nagar main road in Kalapet assembly Constituency.


As per the Revenue Records, this pond is situated at R.S. No. 41/1 of Alankuppam Revenue Village to an extent of 02-17-00 HAC.

This is a rain water catchment pond. At present this pond is dry and free from encroachments. If desilting work is done in this pond before the forthcoming monsoon period, this will increase the storage capacity of the pond and the ground water table will be increased which inturn increase the yield of the borewells which are adjacent to this pond which are used for drinking water supply and agriculture.

Proposal

1. Desilting of pond	– Rs. 6,00,000
2. Strengthening of bund	– Rs. 2,00,000
3. Cleaning the inlet channel	<u>– Rs. 1,50,000</u>
Total	<u>– Rs. 9,50,000</u>

FMB Sketch:



Existing condition of Pillaiyarkulam and its Google Location:



4. Vannarakuttai, Eastern side of Irumbai - Nesal road, Alankuppam.

Vannarakuttai is located at Alankuppam on the Eastern side of the Irumbai-Nesal road in Kalapet Assembly Constituency.

As per the Revenue Records, this pond is situated at R.S. No. 51/2 of Alankuppam Revenue Village to an extent of 00-14-00HAC.


This is a rain water catchment pond. At present, during the recent intermittent downpour, this pond is stored with full capacity of water and is free from encroachments. At present, desilting work is not required.

Proposal

No Proposal

Desilting of pond is not proposed at present, since water is stored with full capacity.

FMB Sketch:



Existing condition of VannaraKuttai and its Google Location:



5. Velankannikulam, Opp to Angalammankoil, Irumbai road, Alankuppam

Velankannikulam is located at Alankuppam opposite to Angalamman temple on the Eastern side of the Irumbai road in Kalapet Assembly Constituency.

As per the Revenue Records, this pond is situated at R.S. No. 69/1 of Alankuppam Revenue Village to an extent of 02-33-00 HAC.

This is a rain water catchment pond. At present this pond is dry and free from encroachments. If desilting work is done in this pond before the forthcoming monsoon period, this will increase the storage capacity of the pond and the ground water table will be increased which in turn increase the yield of three borewells which are adjacent to this pond which are used for drinking water supply and agriculture.

Proposal

1. Desilting of pond	– Rs. 7,50,000
2. Strengthening of bund	<u>– Rs. 1,50,000</u>
Total	<u>– Rs. 9,00,000</u>

ALANKUPPAM [19]

Scale : 1 : 2000

[illegible]

Existing condition of Velankannikulam and its Google Location:



6. Kainthakuttai, Opposite to Law College, Peria Kalapet

Kainthakuttai is located at Periakalapet opposite to Law College on the Northern side of Mathur road in Kalapet Assembly Constituency.

As per the Revenue Records, this pond is situated at R.S. No. 96/9 of Kalapet Revenue Village to an extent of 00-47-00 HAC.


This is a rain water catchment pond. At present there is water in this pond and free from encroachments. The waste water let out from the Tsunami quarters at Periakalapet are stored in this pond as there is no other alternate way for disposal.

Proposal


No proposal

This pond is not proposed for desilting, since there is no possibility to divert the waste water which are being collected in this pond.

FMB Sketch:



Existing condition of Kainthakuttai and its Google location:



7. Kulam, Opposite to Law College, Peria Kalapet.

Kulam is located at Peria Kalapet opposite to Law College on the Northern side of Mathur road in Kalapet Assembly Constituency.

As per the Revenue Records, this pond is situated at R.S. No. 96/10 of Kalapet Revenue Village to an extent of 00-53-00 HAC.


At present, cement concrete pavement is existing in a portion of pond and is used as Kalam (drying yard). Also, a portion of pond is encroached by Anjeneya temple. Desilting is not possible in the remaining portion of the pond at present since there is no possibility to divert the waste water which is stored in this pond.

Proposal

No proposal

Desilting work is not proposed in this pond at present, since Anjaneyar temple and Kalam (drying yard) are in existence in this pond.

FMB Sketch:



Existing condition of Kulam and its Google Location:



8. Gangaammankulam, Eastern side of ECR, Ganapathichettykulam,
Near Gangaiamman temple.

Gangaammankulam is located on the Eastern side of ECR, near Gangaiamman temple at Ganapathichettykulam in Kalapet Assembly Constituency.


As per the Revenue Records, this pond is situated at R.S. No. 160/3 of Kalapet Revenue Village to an extent of 00-38-00 HAC.

This is a rain water catchment pond. At present this pond is dry and free from encroachments. If desilting work is done in this pond before the forthcoming monsoon period, this will increase the storage capacity of the pond and the ground water table will be increased which inturn increase the yield of the borewells which are adjacent to this pond which are used for drinking water supply.

Proposal

1. Desilting of pond	– Rs. 4,00,000
2. Strengthening of bund	– Rs. 1,00,000
3. Construction of inlet channel	<u>– Rs. 2,50,000</u>
Total	<u>– Rs. 7,50,000</u>

FMB Sketch:



Existing condition of Gangaiamman Kulam and its Google Location:



9. Kalapet Nedugkulam, Eastern side of ECR, Opp. to Selliammankoil, Peria Kalapet.

Kalapet Nedugkulam is located on the Eastern side of ECR, opposite to Selliammankoil at Peria Kalapet in Kalapet Assembly Constituency.

As per the Revenue Records, this pond is situated at R.S. No. 236/2 of Kalapet Revenue Village to an extent of 00-81-00 HAC.

This is a rain water catchment pond. At present this pond is dry and free from encroachments. This pond is also used for the Balamurugan temple functions during temple festivals.


A portion of the pond along the western side was already converted into ECR for widening purpose. Further, this Municipality had already issued NOC to the Balamurugan Temple Panchayat for renovating this pond. The work includes desilting, providing pathways, steps etc. and the work is in progress.

Proposal

No proposal

This pond is not proposed at present, since rejuvenation work is in progress which is executed by Balamurugan Temple Panchayat at Periakalapet based on the NOC issued by this Municipality.

FMB Sketch:



Existing condition of Kalapet Nedugkulam and its Google Location:



10. Poiyakulam, Pakkamudayanpet

This pond is located at Pakkamudayanpet in Thattanchavady assembly constituency. It is situated at R.S. No.247/2 of Thattanchavady revenue village to an extent of 0-81-00 H.A.C. At present this pond is completely encroached by houses.

Proposal


No proposal

This pond is not proposed for desilting, as it is completely encroached by houses.

District : Puducherry
 Sub : Guignart
 Page : THATTANCHAVADI [34]

Scale : 1 : 1000

V.NO. 38. SARAM



TALUK COPY

		Ladder		
A	72.8	B	30.6	C
		(118.0)		
		53.4		
		22.4		
		D		
B	1.0	(78.0)	3.0	9
		48.2		
		23.4		
		22.8		
		A		
		B	1.8	6
		(88.2)		
		47.2		
		C		
		D		
B	25.4	(118.4)	73.4	7
		73.4		
		61.8		
		43.4		
		32.8		
3	27.2	34.0	57.6	5
		1		

Existing condition of Poiyakulam and its Google Location:



11. Vannankulam, Southern side of Vazhudavur road and Angalammankoil


This pond is located at on the Southern side of Vazhudavur road and Angalamman temple in Indira Nagar assembly constituency. It is situated at R.S. No. 11/1 of Oulgaret revenue village to an extent of 00-36-50 H.A.C. At present there are 9 nos of RCC roofed house encroachments. The drainage water from the surrounding areas are stored in this pond.

Proposal


No Proposal

This pond is not proposed for desilting, since there are 9 nos of encroachments. Further, drainage water is stored in this pond and there is no possibility for its diversion.

FMB Sketch:



Existing condition of Vannankulam and its Google Location:



12. Thakanam kulam, Southern side of Vazhudavur road,

Backside of Sri Ram Thirumana Nilayam

This pond is located at on the Southern side of Vazhudavur road, backside of Sri Ram Thirumana Nilayam in Indira Nagar assembly constituency. It is situated at R.S. No. 14/1 of Oulgaret revenue village to an extent of 00-31-00 H.A.C. At present there are 8 nos of RCC roofed house encroachments. The drainage water from the surrounding areas are stored in this pond.

Proposal

No proposal

This pond is not proposed for desilting, since there are 8 nos of encroachments. Further, drainage water is stored in this pond and there is no possibility for its diversion.

District : Puducherry

Taluk : Oulgaret

Village : OULGARET [35]

Survey No : 14

Area : Hect 01 Ares 89.50

Scale : 1 : 1000

		Ladder	
		D	
		(156.0)	
		88.8	4.2
		91.8	2.8
		37.0	
		C	
		(178.2)	
		131.8	
		106.0	
		95.2	11.2
		86.2	
		88.8	15.6
		83.2	
		40.8	24.8
		40.0	2.8
		32.8	1.8
		E	
		F	
		(99.8)	
		88.4	
		87.8	
		83.2	
		13.5	
		12.4	
		A	
		(110.8)	
		28.0	
		C	
		(157.6)	
		123.4	8.4
		126.6	7.4
		123.6	4.4
		72.8	
		61.0	3.2
		83.6	
		99.0	7.2
		52.8	58.4
		51.2	
		48.0	
		B	
		(78.8)	
		51.4	
		A	
		(98.2)	
		98.8	
		70.2	
		C	

Existing condition of Thakanam Kulam and its Google Location:




13. Kulam, Muthupillaipalayam

This pond is situated in R.S. No. 71/3 Oulgaret Revenue Village. The extent of the pond is 00.08.00 H.A.C. The location of the pond is in Muthupillaipalayam village in Oulgaret Constituency. Now there is no pond in this location. There is one overhead tank and one Anganvadi building are existing in the location.


Proposal:

There is no proposal for desilting, as there is no pond at site, in which OHT and Anganwadi buildings are located.

FMB Sketch:



Existing condition of Kulam and its Google Location:



14. Thamaraikulam, Muthupillaipalayam

This pond is situated in R.S. No. 88/1 in Oulgaret Revenue Village. The extent of the pond is 00.31.00 H.A.C. The location of pond is at Shanmuga Nagar near Muthupillaipalayam in Oulgaret Assembly Constituency. The boundaries of the pond are to be demarcated. De-silting is required. At present there is some rain water in the pond.


Proposals

The proposal for Renovation and the total amount required is as below:


- | | |
|--------------------------------------|--------------------------|
| 1. For de- silting | – Rs. 5,00,000/-. |
| 2. For bund works and stone pitching | – Rs. 25,00,000/-. |
| 3. For constructing steps | – <u>Rs. 2,00,000/-.</u> |
| Total | - <u>Rs. 32,00,000/-</u> |

But, as a first step at least the desilting and strengthening of bund has to be taken up immediately before the monsoon period for which an amount of **Rs. 7.00 lakhs** is required.

FMB Sketch:



Existing condition of Thamaraikulam and its Google Location:




15. Kulam, Southern side of Christ College

This pond is situated in R.S. No. 89/1 in Oulgaret Revenue Village. The extent of the pond is 00.11.50 H.A.C. The location of pond is at Northern side of Roja Nagar and Western side Pavendar Nagar park area in Oulgaret Assembly Constituency. The pond is surrounded by private land and there is no direct approach to the pond. At present there is some rain water in the pond.

Proposal:

No proposal

Desilting is not proposed as there is no approach to the pond which is locked by private lands.



Existing condition of Kulam and its Google Location:



16. Kannikuttai, Backside of Vasantharaja Theatre, Moolakulam

This pond is situated in R.S. No. 105/4 in Oulgaret Revenue Village in Oulgaret Assembly Constituency. The extent of the pond is 00.05.00 H.A.C. There is encroachment in the pond and the same is to be demarcated on the field. At present there is no water in the pond. This pond is surrounded by private land and there is no direct approach to the pond.

Proposal

No proposal

Desilting is not proposed as there is no approach to the pond which is locked by private lands.

FMB Sketch:

District : Puducherry


Tatuk : Oulgarat

Village : OULGARET (35)

Survey No : 105

Area : Hect 02 Ares 20.00

Scale : 1 : 1000



Ladder					Ladder				
		G			10	20.2	114.4	4.4	11
		(178.6)				112.8			
23	36.6	163.8			8	20.0	112.0		
22	36.6	127.2			8	19.0	102.2		
21	9.8	60.2			6	5.8	101.6	24.8	7
		C					84.8		
		F					B		
		(185.2)					D		
20	3.8	106.4					(90.4)		
		105.8	8.0	10			39.6	13.0	5
		26.4	3.8	10			C		
		E					D		
		(182.4)					(203.6)		
		D					193.2	20.2	6
		(182.4)					170.6	2.0	4
G	87.4	158.2			8	104.0	58.8		
		144.8	4.8	17	3	32.2	54.8		
	13.0	135.8					F		
	28.0	128.8					(117.2)		
	4.0	120.0					13.0	32.8	A
	8.0	154.4					B		
18	9.8	139.2					A		
15	22.0	135.2					(109.6)		
14	31.4	128.0			7	2.0	101.6		
13	3.0	116.0					77.2	2.8	8
12	26.0	116.0					F		

R-7-140-125/126/127, 128/129 Calculations are
checked as per R-7-140-120/121 by dt. rs/aa/bc

Un. 

Existing condition of Kannikuttai and its Google Location:



17. Moolakulam, Moolakulam

This pond is situated in Moolakulam at R.S. No. 106/1 of Oulgaret Revenue Village in Oulgaret Assembly Constituency. The extent of the pond is around 00.49.80 H.A.C. There is encroachment around the pond and the same is to be demarcated on the field. De-silting is not required. At present there is no water in the pond. Sullage water not mixed in the pond.

Proposal:

No proposal

There is no proposal for desilting at present, as the pond is already clean.

District : Puducherry

Taluk : Oulgaret

Village : OULGARET [35]

Survey No : 106

Area : Hect 01 Ares 72.50

Scale : 1 : 1000

TALUK COPY

Handwritten Notes:

Hungon
 do. Subdivision 98949534
 No 37, I Cressis
 fourmpon ugon
 Hach karlan
 Pondy - 10

Vaithyanathan
 do. Komand Postappon
 14 66, 1 1000
 J. J. Nagam.

Table:

Ladder			
A	57.5	B (168.8)	
		90.8	
		E	
		A	
		(142.4)	
		92.2	
5	7.6	29.0	5.6 F
4	1.5	26.0	
		E	
		D	
		(245.4)	
		158.0	100.2 E
		188.8	LINE C
		B	
		C	
		(196.6)	
3	0.9	6.0	
		E	
		D	
		(132.0)	11.2 J
1	38.2	120.4	
		28.2	
		E	
		(90.4)	
		A	

Existing condition of Moolakulam and its Google Location:



18. Alli Kuttai, Adikesavan Nagar, Moolakulam


This pond is situated in R.S. No. 115/1 in Oulgaret Revenue Village. The extent of the pond is 00.15.00 H.A.C. The location of pond is at Southern end of Adikesavan Nagar in Oulgaret Assembly Constituency. There is encroachment noted in the pond and the same is to be demarcated. At present there is no water in the pond.

Proposal:

No proposal

Desilting is not proposed at present, as there are encroachments and the boundaries are to be demarcated.

FMB Sketch:



Existing condition of Alli Kuttai and its Google Location:



19. Thaganakuttai, Thakkakuttai, Arumbarthapuram

This pond is situated in R.S. No. 128/2 in Oulgaret Revenue Village in Oulgaret Assembly Constituency. The extent of the pond is 00.92.00 H.A.C. Free house site patta were issued around the pond. There is some encroachment also noted around the pond and the same is to be demarcated on the field. De-silting is required. At present there is sewage water mixed in the pond.

Proposals


Proposal for Renovation and amount are as below:

1. For de- silting	– Rs. 5,00,000/-.
2. For bund works and stone pitching	– Rs. 30,00,000/-.
3. For constructing steps	– Rs. 2,00,000/-.
4. For constructing inlet and out let channel	– Rs. 5,00,000/-.
5. For de watering	– <u>Rs. 1,00,000/-.</u>
Total	– <u>Rs. 43,00,000/-.</u>


NOC was issued by this Municipality to PADCO for desilting / Rejuvenation of pond. Work will be taken up by PADCO during the financial year 2019-20.

But, as a first step atleast the desilting and strengthening of bunds has to be taken up immediately before the monsoon period for which an amount of **Rs. 8.00 lakhs** is required.

FMB Sketch:



Existing condition of Thaganakuttai and its Google Location:



20. Ayee Kulam, Muthiraiyarpalayam

This pond is located at Muthirapalayam in Indira Nagar assembly constituency. It is situated at R.S. No. 186/1 of Oulgaret revenue village to an extent of 00-94-30 H.A.C. At present there are 7 nos of RCC roofed house encroachments. This is rainwater catchment pond. At present this pond is being maintained by PWD.

Proposal

No proposal


Desilting is not proposed by this Municipality, as this pond is maintained by PWD.

FMB Sketch:

District : Puducherry
Taluk : Oulgaret
Village : OULGARET [35]


Survey No : 185
Area : Hect 01 Ares 85.80
Scale : 1 : 1000

V.NO: 34 THATTANCHAVADY



Ladder									
	3				45.0	87.0			
	(11.0)					87.0		60.0	
	3.0	3.8	18		80.0	63.0			
	b				15.0	69.0		50.0	
	(122.2)					32.4		20.0	
	72.2	21.1	17			0			
	72.2	2.0	16			0			
	63.0	21.2	15			0			
	63.0	2.8	18			(144.0)			
	a				5	20.6			
	g					77.8			
	(173.0)				5	13.0		38.0	C
	106.8	36.0	13		1.6	16.6			
	98.8	22.2	12			0			
	88.4	13.4	11			0			
	48.6	9.2	10			(137.2)			
	30.8	11.4	9			81.8		2.4	4
	16.0	7.0	14			C			
	A					D			
	(192.2)					(32.4)			
	67.4					81.8		3.2	3
	39.2	28.2	6			E			
	19.8	8.2	7		2	(113.6)			
	124.0				2.8	34.8			
	124.0	15.0				31.4		5.8	1
						A			

Existing condition of Ayeekulam and its Google Location:



21. Vannankulam, Govindanpet


This pond is located at Govindanpet in Indira Nagar assembly constituency. It is situated at R.S. No. 187/2A of Oulgaret revenue village to an extent of 00-59-20 H.A.C. At present, there are 11 nos of RCC roofed house encroachments. The drainage water from the surrounding areas are stored in this pond.

Proposal


Work proposed to divert the drainage water to the adjacent canal and for desilting for an amount of Rs. 30.00 lakhs.

But, as a first step, bailing out of water and desilting works have to be taken up immediately before the monsoon period for which an amount of **Rs. 10.00 lakhs** is required.

FMB Sketch:



Existing condition of Vannankulam and its Google Location:



22. Peria Kulam, Kavundanpalayam

This pond is located at Kavundanpalayam in Thattanchavady assembly constituency. It is situated at R.S. No.26/1 of Reddiarpalayam revenue village to an extent of 00-27-00 H.A.C. This pond is under the possession of temple authority, partly encroached by houses and completely filled by earth.


Proposal

No proposal

This pond is not proposed, since this pond is completely filled with earth which is under the possession of adjacent temple authority.

Pincode : 605 006
District : Puducherry
Taluk : Cuddalore
Village : REDDIARPALAYAM [36]

Scale : 1 : 500



Existing condition of Peria Kulam and its Google Location:



23. Vannankulam, Kamban Nagar, Reddiarpalayam

This pond is situated in R.S.No.93/1 in Reddiarpalayam Revenue Village. The extent of the pond is 00.22.50 H.A.C. The location of pond is at 1st Cross Street, Kamban Nagar, Reddiarpalayam, in Oulgaret Assembly constituency. At North- East corner a bore well has been erected and partly filled for construction of Pump house by the Public Works Department, Puducherry. There are some encroachments around the Kulam encroaching inlet and outlet channel. At present there is no water in the Kulam, the sullage water is not mixed and the de silting of Kulam is required.

Proposal:

No proposal

This pond is not proposed for desilting at present, since there are some encroachments around the pond and also in the inlet/outlet channel.

Page : REDDIARPALAYAM [35]

Scale : 1 : 1000



Existing condition of Vannankulam and its Google Location:



24. Periyavana Madu, Behind the Parvathi Thirumana Nilayam

This pond is located at Behind the Parvathi Thirumana Nilayam, Pakkamudayanpet in Thattanchavady assembly constituency. This pond is situated in R.S. No. 64/4 of Saram revenue village to an extent of 00-54-50 H.A.C.

Proposal

The existing pond is proposed to improve by

1. Desilting and strengthening of bund - Rs. 10,00,000.
2. Filling gravel for forming bund - Rs. 10,00,000.
3. Walkway to a length of 200m - Rs. 4,00,000.
4. 15 Nos. of Benches and LED street lights-Rs. 2,25,000

Total Cost: Rs.26,25,000

But, as a first step atleast the desilting has to be taken up immediately before the monsoon period for which an amount of **Rs. 10.00 lakhs** is required.


FMB Sketch:

District : Puducherry
Taluk : Oulgaret
Village : SARAM [38]

Survey No : 64

Area : Hect 01 Ares 14.70

Scale : 1 : 1000



Existing condition of Periyavana Madu and its Google Location:



25. Krishnan Kuttai, Pakkamudayanpet


This pond is located at Pakkamudayanpet in Thattanchavady assembly constituency. This pond is situated in R.S. No. 66/1 of Saram revenue village to an extent of 00-17-00 H.A.C. Krishnan Kuttai is now converted into Sainik Welfare Office and Jawan Bhavan building is existing.

Proposal

No Proposal

This pond can't be desilted since there is no pond in site and Jawan Bhavan building is existing in this pond.

FMB Sketch:



Existing condition of Krishnan Kuttai and its Google Location:



26. Poonkulam, Opp. to Hotel Annamalai. Adj. to Subramaniaswamy Koil, Saram

This pond is located opposite to Hotel Annamalai and adjacent to Subramaniaswamy temple, Saram at R.S. No.80/4 of Saram revenue village in Kamaraj Nagar to an extent of 00-20-50 HAC. This pond is completely filled with earth and the boundaries are encroached by Government buildings and individuals. Desilting can be done after eviction of encroachments.

Proposal

No proposal

This pond is not proposed for desilting, since this pond is completely encroached.

FMB Sketch:

Plot : Puducherry
 Loc : Oulgaret
 Plot : SARAM [38]

Survey No : 80

Area : Hect 01 Ares 17,10

Scale : 1 : 1000



Ladder				
		A		
		(55.0)		
21	2.0	44.8		
		B		
		C		
		(50.0)		
20	1.2	16.0		
		E		
		C		
		(140.0)		
		28.4	40.5	D
		E		
		(75.0)		
19	15.5	63.0		
18	3.2	29.6		
		A		
		C		
		(118.0)		
17	17.4	62.8		
25	17.5	63.0		
16	16.0	62.0		
15	23.4	88.4		
14	17.4	75.0		
	School	9.0	68.8	
	"	17.2	65.8	
	"	3.2	62.8	
13	2.4	60.0		
12	16.4	55.8		
		D		
		C		
		(189.2)		
		68.8	24.5	10
24	1.8	68.8		
23	1.6	68.0		
		62.4	22.4	b1
		61.4	19.0	9
		68.8	23.8	8
		65.2	23.8	7
		61.0	41.4	
		66.0	5.8	22
		70.4	41.8	5
		65.2	17.4	4
		65.0	68.2	3
		45.0	61.4	E
8	51.4	20.0		
2	12.8	19.2		
1	13.2	14.8		
		A		

Existing condition of Poonkulam and its Google Location:



27. Kuttai, Adj. to ECR Opp. to Sree Raja Rajeswari Thirumana Nilayam


This pond is located at adjacent to ECR and opposite to Sree Raja Rajeswari Thirumana Nilayam in Thattanchavady assembly Constituency. It is situated at R.S. No.146/6 of Saram revenue village to an extent of 00-09-50 H.A.C. This is rain water catchment pond having no access. But, desilting could be done through the private vacant land with the permission of land owner.

Proposal

For desilting and strengthening of bunds – **Rs. 5,00,000/-**

Puducherry
Culgarat
SARAM [38]

Scale : 1 : 1000

[illegible]

Existing condition of Kuttai and its Google Location:



28. Paracheri Maduvu, Opp. to Latha Steel House, ECR

This pond is located opposite to Latha Steel House at ECR in Thattanchavady assembly Constituency. It is situated at R.S. No.147/2 of Saram revenue village to an extent of 00-28-50 H.A.C. At present free house site patta was issued in this pond.


Proposal

No proposal

There is no proposal for desilting as free house site patta was issued in this pond.

Puducherry
Olgaret
SARAM [38]

Scale : 1 : 1000



Existing condition of Paracheri Maduvu and its Google Location:



29. Kuttai, Opp to Latha Steel House, ECR

This pond is located opposite to Latha Steel House at ECR in Thattanchavady assembly Constituency. It is situated at R.S. No.147/9 of Saram revenue village to an extent of 00-41-50 H.A.C. At present Nagamuthu Mariamman temple is existing in this pond.


Proposal

No proposal

This pond can't be desilted, since Nagamuthu Mariamman temple is existing in this pond.

Puducherry
Olgareet
SARAM [38]

Scale : 1 : 1000



Existing condition of Kuttai and its Google Location:



30. Vengataraiya Pillai Maduvu, Dobighana


This pond is situated in Dobighana at R.S. No. 174/1 in Saram Revenue Village in Lawspet Assembly Constituency. The extent of the pond is 00.32.00 H.A.C. At present, Sankara Vidhyalaya School is existing.

Proposals


No Proposal

Desilting can't be proposed, since Sankara Vidhyalaya School is existing in this pond.

FMB Sketch:



Existing condition of Vengataraiya Pillai Maduvu and its Google Location:



31. Vengadasalam Pillai Madu, Adjacent to ECR

This pond is situated in R.S. No. 175 in Saram Revenue Village in Lawspet Assembly Constituency. The extent of the pond is 00.70.00 H.A.C. At present there is some rain water stagnation in the pond. A portion of this pond was allotted to Lawspet Police Station, Census Office, Communist Office and Free patta. De-silting is required for the balance portion of pond.

Proposals

Proposal for Renovation and amount are as below:

1. For de- silting	– Rs. 5,00,000/-.
2. For bund works and stone pitching	– Rs. 15,00,000 /-.
3. For constructing steps	– Rs. 2,00,000/-.
4. For constructing inlet and outlet channel	– <u>Rs. 13,00,000/-.</u>
Total	– <u>Rs.35,00,000 /-.</u>

But, as a first step atleast the desilting has to be taken up immediately before the monsoon period for which an amount of **Rs. 7.50 lakhs** is required.

FMB Sketch:

District : Puducherry

Taluk : Oulgaret


Village : SARAM [38]

Survey No : 175

Area : Hect 00 Ares 70.00

Scale : 1 : 1000


V.A.O. COPY



V.A.O. COPY

Ladder												
		10				(10.0)					155.2	2.5
11	52.0	109.0			3	5.0	98.0		D	68.2	115.2	
10	52.0	76.4				7.6	94.8			38.0	56.8	
9	48.8	65.4					51.0	15.0	C	48.0	37.4	
8	39.4	49.8			2	6.0	14.4		E	39.0	32.0	
7	13.0	14.2					8.0	8.0			20.0	11.0
6	0.8	8.0									19.0	30.8
		I								1.0	8.0	
		E									A	
		(54.8)			1	2.6	(10.4)				E	
5	9.2	37.0					O				(54.0)	
	4.0	36.0					F				F	
		28.0					(199.2)				(18.0)	
4	8.0	12.2	10.0				188.0	18.0	G		G	
		O			6	35.2	150.0				(39.0)	
						3.0	190.0				H	

Existing condition of Vengadasalam Pillai Madu and its Google Location:



Imagery ©2019 CNES / Airbus, DigitalGlobe, Maxar Technologies 20 m

32. Vannankulam, Maduvupet

This pond is located adjacent to Krishna Nagar main road at Maduvupet in Lawspet assembly Constituency. It is situated at R.S. No.219/2 of Saram revenue village to an extent of 00-37-50 H.A.C. At present, partly free house site patta was issued in this pond.

Proposal

No Proposal

There is no proposal to desilt this pond, since free house site patta was issued in this pond.

istrict : Puducherry

uk : Oulgaret

age : SARAM [38]

Survey No : 219

Area : Hect 01 Ares 57.00

Scale : 1 : 1000

V.A.O. COPY

218

221

220


169

168

183

		Ladder	
		C	
		(100.6)	
20	8.2	75.0	39.2
		13.4	
		D	
		F	
		(98.4)	
E	13.0	44.0	
		C	
		F	
		(117.4)	
		112.2	3.4
16	13.4	83.8	
17	3.4	75.0	
16	7.8	65.0	
15	9.0	35.6	
		A	
		B	
		(165.0)	
A	76.6	69.8	
		F	
		B	
		(104.4)	
		61.8	4.2
		8.8	7.6
		A	
		C	
		(94.8)	
		56.3	LINE
11	0.6	45.0	
10	0.2	13.9	
		D	
		148.9	5.4
		C	
		(144.8)	
		139.4	12.2
		188.4	11.2
		103.2	7.8
		103.2	11.8
		80.0	8.0
3	7.8	84.4	
2	11.6	91.2	
1	3.4	22.6	
		B	

Existing condition of Vannan Kulam and its Google Location:



33. Oural Kuttai, Opp. to Orange Restaurant at ECR


This pond is located opposite to Orange Restaurant at ECR in Kamaraj Nagar assembly Constituency. It is situated at R.S. No.222/2 of Saram revenue village to an extent of 00-20-50 H.A.C. At present this pond is converted as ECR.

Proposal

No proposal

As this pond was converted as ECR, there is no proposal for desilting.

FMB Sketch:



Existing condition of Oural Kuttai and its Google Location:



34. Chetty Kulam, Backside of Old Ambiga Theatre


This pond is located backside of Old Ambika theatre in Kamaraj Nagar assembly Constituency. It is situated at R.S. No.281/2 of Saram revenue village to an extent of 00-17-00 H.A.C. At present PWD sewage pump house is located.

Proposal

No proposal

Desilting work can't be done since PWD sewage pump house is located

Existing condition of Chetty Kulam and its Google Location:



35. Pillaiyarkoil Kulam, Opp. to Lawspet Police Station

This pond is situated in R.S. No. 109/1 in Karuvadikuppam Revenue Village. The extent of the pond is 00.40.00 H.A.C. The location of the pond is opposite to Lawspet Police Station on the Southern Side of Mahaveer Nagar. Cleaning of the pond was carried out. De-silting of pond is required. At present there is some rain water stagnation in the pond. There is encroachment noted and demarcation to be carried out soon.

Proposals

Proposal for Renovation and amount are as below:

1. For de- silting	– Rs. 8,00,000 /-.
2. For bund works and stone pitching	– Rs. 62,00,000/-.
3. For constructing steps	– Rs. 5,00,000/-.
4. For constructing inlet and outlet channel	– Rs. 8,00,000/-.
5. Lighting and Bench Works	– <u>Rs. 5,00,000/-.</u>
Total	– <u>Rs. 88,00,000/-.</u>

But, as a first step atleast the desilting has to be taken up immediately before the monsoon period for which an amount of **Rs. 9.00 lakhs** is required.


FMB Sketch:

District : Puducherry
Taluk : Cuddalore
Village : KARUVADIKUPPAM [39]

Survey No : 109

Area : Hect 00 Area 85.00

Scale : 1 : 1000




Grp { 100/1 - 00 10 100 100 - 0000 00000000
100/5 - 00 11 10 100
100/4 - 00 11 10 100

(c) — 11.3 + 30.0 + 30.0 +

		Ladder	
		C (96.0)	12.0
		72.4	5.5
WD.T		70.0	5.0
WD.T		43.0	15.0
		46.0	2.4
		46.8	24.0
		45.2	
		A	
		C	
		(138.0)	
WD.T		124.0	2.0
WD.T		42.8	5.8
		37.8	1.8
TEMPLE		33.0	2.8
TEMPLE		26.8	1.0
		B	
		(132.0)	
		90.2	4.0
		27.8	1.2
		85.8	0.4
		13.0	0.6
		2.8	1.8
		A	

Existing condition of Pillaiyarkoil Kulam and its Google Location:



36. Villi Madu, Adjacent to Jayaram Garden, ECR

Villi Madu is located near Jayaram Garden, behind MVR hospital at Karuvadikuppam near ECR in Kalapet Assembly Constituency.

As per the Revenue Records, this pond is situated at R.S. No. 139/4 of Karuvadikuppam Revenue Village to an extent of 00-53-00 HAC.

NOC was issued by this Municipality to PWD for construction of Sewage Treatment Plant / Pump House. At present PWD has constructed Sewage pump house in a portion of the pond and the remaining portion is left for storage of rain water. This is a rain water catchment pond. At present some water is stored in the pond.

Proposal

No proposal

Desilting is not proposed since NOC was issued for construction of Sewage Pump house/Treatment plant by PWD.


FMB Sketch:

District : Puducherry
Taluk : Oulgaret
Village : KARUVADIKUPPAM [39]

Survey No : 139

Area : Hect 01 Ares 28.50

Scale : 1 : 1000



Ladder							
20	3.2	A	(125.6)	29	11.2	E	(95.6)
		82.8	11.2	17	14.2	37.8	3.8
		70.4	1.0	16	2.0	31.0	
		61.2	22.0			5.4	
		59.4				F	
		52.8	7.6	15	11.6	D	
		51.2				(155.2)	
F	48.0	C	(102.4)			159.0	
		33.4				122.8	2.8
		B	(112.8)	6	74.2	70.6	
		21.2	24.8	13	17.6	68.2	
		D		12	32.4	44.6	
		F	(97.4)	11	36.6	39.6	
		54.6	5.6	10	13.2	7.2	
		50.8	3.2			E	
		41.8	3.2			B	
		7.0		9	2.2	(94.4)	
		6.0	1.4			92.4	
		A				85.8	3.8
				6	0.4	74.0	
				5	54.2	67.8	
						65.0	
						C	
						B	
						(98.4)	
						77.0	
						75.8	
						60.6	
						22.0	
						2.8	
						A	
							1.6
							100.4

Existing condition of Villi Madu and its Google Location:



37. Vannan Madu, Adj. to Vivekanada HSS, Northern side of ECR


This pond is located adjacent to Vivekanada HSS, Northern side of ECR in Lawspet assembly Constituency. It is situated at R.S. No.140/1 of Karuvadikuppam revenue village to an extent of 00-29-50 H.A.C. At present ECHS Poly Clinic and PWD Pump house are located in this pond.

Proposal

No proposal

Desilting can't be done since ECHS Polyclinic and PWD pump house are located in this pond.

FMB Sketch:



Existing condition of Vannan Madu and its Google Location:



CONCLUSION:

Out of 37 ponds, based on the site condition, this Municipality has proposed to rejuvenate / desilt 12 number of ponds, for which preliminary estimates are prepared for an amount of Rs.303.00 lakhs which includes various works viz., desilting, strengthening of bunds, construction of steps, stone pitching, walking track, benches, lighting, inlet/outlet channels etc.

But, as a first step at least the desilting has to be taken up immediately for all the **12 ponds** before the monsoon period for which an amount of **Rs. 100.25 lakhs** is required. as detailed in the **Annexure – A**.

The remaining ponds i.e., 25 nos are not proposed at present, due to various reasons as mentioned in the **Annexure – B**.

By rejuvenating / desilting 12 nos of ponds, the ground water table will be increased substantially which will be benefited by the people for drinking, agriculture purposes etc. which is one of the major interventions in Jal Shakti Abhiyan.

These activities will be executed with the involvement of local residents, Resident Welfare Association, Self Help Group, NSS Students, etc., with the participation of local MLA / MP to create much awareness among the people regarding the importance of preserving the water bodies.

Annexure – A
Abstract for Proposed Estimates

Sl. No.	Name of the Pond	Constituency	Revenue Village	R.S.No.	Extent H.A.C	Funds required for Rejuvenation /Desilting (Rs. in Lakhs)	Ref. P.No.
1	Pillaiyarkoil Kulam, Opp. to Lawspet Police Station	Lawspet	Karuvadikuppam	109/1	00-40-00	9.00	107
2	Periavana madu, behind Parvathy Thirumana Nilayam	Thattanchavady	Saram	64/4	00-54-50	10.00	74
3	Vannan Kulam, Govindanpet	Indira Nagar	Oulgaret	187/2A	00-59-20	10.00	65
4	Vengadasalam Pillai Madu near Maduvupet	Lawspet	Saram	175	00-70-00	7.50	95
5	Kuttai, Adj. to ECR and Opp. to Sree Raja Rajeswari Thirumana Nilayam	Pakkamudayanpet	Saram	146/6	00-09-50	5.00	83
6	Thamarai kulam, Muthupillaipalayam	Oulgaret	Oulgaret	88/1	00-31-00	7.00	44
7	Thamarai kulam, Sanjeevi Nagar	Kalapet	Alankuppam	18/14	01-63-50	10.00	5
8	Thanthiriyar Kulam, Alankuppam	Kalapet	Alankuppam	35/2	01-36-00	7.75	8
9	Pillaiyarkulam, Alankuppam	Kalapet	Alankuppam	41/1	02-17-00	9.50	11
10	Velankanni Kulam, Alankuppam	Kalapet	Alankuppam	69/1	02-33-00	9.00	17
11	Gangaiammankoil Kulam, Ganapathichettykulam	Kalapet	Kalapet	160/3	00-38-00	7.50	26
12	Thagana Kuttai, Thakkakuttai	Oulgaret	Oulgaret	128/2	00-92-00	8.00	59
Total						100.25	

Annexure – B
Abstract of Non – Proposed ponds

Sl. No.	Name of the Pond	Constituency	Name of the Revenue Village	R.S.No.	Extent H.A.C	Reason for Not Proposed	Ref. P. No.
1	Vannara Kuttai, Eastern side of Irumbai - Nesal road	Kalapet	Alankuppam	51/2	00-14-00	Full capacity of water at present	14
2	Kainthakuttai, Opp. to Law college, Peria Kalapet	Kalapet	Kalapet	96/9	00-47-00	No possibility to divert the waste water	20
3	Kulam, Opp. to Law College, Periakalapet	Kalapet	Kalapet	96/10	00-53-00	Encroached by Anjeneyar Temple and Kalam (drying yard) is also existing	23
4	Kalapet Nedugkulam, Eastern side of ECR	Kalapet	Kalapet	236/2	00-81-00	Work is in progress by Bala Murugan temple panchayat based on the NOC issued by this Municipality	29
5	Poiya Kulam, Pakkumudayanpet	Thattanchavady	Thattanchavady	247/2	00-81-00	Completely encroached by houses	32
6	Kulam, Southern side of Christ College	Oulgaret	Oulgaret	89/1	00-11-50	No access to pond and locked by private lands	47
7	Moolakulam at Moolakulam	Oulgaret	Oulgaret	106/1	00-49-80	Clean at present	53
8	Alli Kuttai, Adikesavan Nagar	Oulgaret	Oulgaret	115/1	00-15-00	Due to encroachments	56

9	Vannan Kulam, Kamban Nagar, Reddiarpalayam	Oulgaret	Oulgaret	93/1	00-22-50	Due to encroachments	71
10	Vannan Kulam, Southern side of Vazhudavur road	Indira Nagar	Oulgaret	11/1	00-36-50	9 Nos of encroachment	35
11	Thakanam Kulam, Southern side of Vazhudavur road	Indira Nagar	Oulgaret	14/1	00-31-00	8 Nos of encroachment	38
12	Kulam, Muthupillaipalayam	Oulgaret	Oulgaret	71/3	00-08-00	OHT & Anganwadi buildings are existing	41
13	Kannikuttai, Backside of Vasantharaja Theatre	Oulgaret	Oulgaret	105/4	00-05-00	No approach to pond. Surrounded by private land	50
14	Ayee Kulam, Muthiraiyarpalayam	Indira Nagar	Oulgaret	186/1	00-94-30	Maintained by PWD	62
15	Peria Kulam, Kavundanpalayam	Thattanchavady	Reddiarpalayam	26/1	00-27-00	Encroached by houses and completely filled with earth	68
16	Krishnan Kuttai, Pakkamudayanpet	Thattanchavady	Saram	66/1	00-17-00	Jawan Bhavan building is existing	77
17	Paracheri Maduvu, Opp. to Latha Steel House	Thattanchavady	Saram	147/2	00-28-50	Free house site patta issued	86
18	Kuttai, Opp. to Latha Steel House	Thattanchavady	Saram	147/9	00-41-50	Nagamuthu Mariamman temple is existing	89
19	Vengataraiya Pillai Maduvu, Dobighana	Lawspeet	Saram	174/1	00-32-00	Sankara Vidhyalaya school is existing	92

20	Vannan Kulam, Maduvupet	Lawspet	Saram	219/2	00-37-50	Free house site patta issued	98
21	Oural Kuttai, Opp. to Orange Restaurant	Kamaraj Nagar	Saram	222/2	00-20-50	Converted as ECR	101
22	Chetty Kulam, Backside of Old Ambiga Theatre	Kamaraj Nagar	Saram	281/2	00-17-00	PWD sewage pump house is existing	104
23	Poonkulam, Opp. to Annamalai Hotel	Kamaraj Nagar	Saram	80/4	00-20-50	Due to encroachments	80
24	Villi Madu, Adj. to Jayaram Garden	Kalapet	Karuvadikuppam	139/4	00-53-00	Handed over to PWD. Sewage pump house is existing	110
25	Vannan Madu, Adj. to Vivekananda HSS	Lawspet	Karuvadikuppam	140/1	00-29-50	ECHS Polyclinic and PWD pump house are existing	113